


NC PIEDMONT HOMEOWNERS


NC CLAY KILLS YOUR BASIN IN 2-3 YEARS

THE MAINTENANCE TRAP CONTRACTORS DON'T MENTION

✓ YEAR 1: CLEAN



✗ YEAR 3: CLOGGED



without annual cleanout →

SAVE THIS BEFORE YOU ACCEPT A QUOTE

THE NUMBERS THAT MATTER

3.5-4.0 IN/HR

NC 10-YEAR STORM

Size for this, not average rain

1,500-2,500 SQ FT

12-INCH GRATE SERVES

With a 4-inch solid outlet

2-3 YEARS

UNTIL CLAY BLOCKS IT

If you skip the annual cleanout

\$150-\$350

BASIN CLEANOUT COST

NC contractor rate per visit



NC PIEDMONT CLAY SETTLES IN THE SUMP

Fine red clay stays suspended in runoff and drops out in the basin. Skip the annual cleanout and a basin partially blocks within 2 to 3 years.



NC GRADE AND HAUL

NCGRADEHAUL.COM

VERIFIED NC CONTRACTORS

Get quotes from verified NC contractors