



NC SILT FENCE INSTALLATION

WRONG STAKE SPACING




FABRIC NOT KEYED




NO INSPECTION RECORD



Permit-risk card
Avg. inspector-
stoppage risk




DOWNSLOPE PLACEMENT



Should be upslope
of disturbed area

TORN FABRIC



Unrepaired gap

Does your site have any of them?

NC Sedimentation and Erosion
Control Act specifies stake spacing,
fabric spec, and keying depth



ncgradeandhaul.com

3 of these 5 failures trigger
an NC inspection stop.